


0+800

$W=0,86 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,02\text{m}^2$

$S_n=0,36\text{m}$




0+900

$W=0,52 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,38\text{m}^2$

$S_n=1,16\text{m}$




1+000

$W=0,50 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,16\text{m}^2$

$S_n=0,46\text{m}$



1+092

$W=0,70 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,14\text{m}^2$

$S_n=0,44\text{m}$

