


0+002

$W=1,87 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,00\text{m}^2$

$S_n=0,00\text{m}$




0+100

$W=0,48\text{m}^2$

$S_w = 2,70\text{m}$

$N=0,00\text{m}^2$

$S_n=0,06\text{m}$




0+200

$W=1,28 \text{ m}^2$

$S_w = 5,36\text{m}$

$N=0,24\text{m}^2$

$S_n=0,72\text{m}$



0+300

$W=0,72 \text{ m}^2$

$S_w = 3,42\text{m}$

$N=0,88\text{m}^2$

$S_n=1,46\text{m}$

