


0+400

$W=0,34 \text{ m}^2$

$S_w = 1,40\text{m}$

$N=0,46\text{m}^2$

$S_n=0,32\text{m}$




0+500

$W=0,34 \text{ m}^2$

$S_w = 1,48\text{m}$

$N=0,40\text{m}^2$

$S_n=0,24\text{m}$




0+600

$W=0,44 \text{ m}^2$

$S_w = 1,28\text{m}$

$N=0,75\text{m}^2$

$S_n=0,90\text{m}$



0+700

$W=0,44 \text{ m}^2$

$S_w = 1,44\text{m}$

$N=0,50\text{m}^2$

$S_n=0,96\text{m}$

