


0+800

$W=0,34 \text{ m}^2$

$S_w = 1,30\text{m}$

$N=0,36\text{m}^2$

$S_n=0,46\text{m}$




0+900

$W=0,32 \text{ m}^2$

$S_w = 1,20\text{m}$

$N=0,26\text{m}^2$

$S_n=0,10\text{m}$




0+950

$W=0,22 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,00\text{m}^2$

$S_n=0,00\text{m}$



1+000

$W=0,00 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,00\text{m}^2$

$S_n=0,00\text{m}$

