


1+092

$W=0,70 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,14\text{m}^2$

$S_n=0,44\text{m}$




1+100

$W=0,16 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,64\text{m}^2$

$S_n=1,16\text{m}$




1+200

$W=0,82 \text{ m}^2$

$S_w = 0,60\text{m}$

$N=0,00\text{m}^2$

$S_n=0,10\text{m}$



1+218

$W=1,06 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,04\text{m}^2$

$S_n=0,18\text{m}$

